

CASPIR Aircraft Accident Cards

Serial: R3413

Title: Avro Anson Mk. I serial:R3413 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-May-13. Anson I s/n R3413. This accident involved 5 people. Bloomfield GL, Davidson CG, Griffiths JO, Mcrae JA, Rennie AR

Keywords: RCAFAnson I,R3413,5 AOS,5 Air Observer School,Rivers Manitoba,1944-May-13,Bloomfield,Davidson,Griffiths,Mcrae,RennieRCAF L20

Created: 1944-05-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#R3413>

ACCIDENT CLASSIFICATION

UNIT 5 A.O.S. Winnipeg	COM. 2	PLACE Rivers, Man	DATE 13-5-44	TIME 0100
A/C TYPE ANSON I		NO. R3413	CRASH CAT. "E"	H.Q. FILE 1300-R3413
		S.E.	M.E. X	DAY
				NIGHT X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
DAVIDSON, C.G.	SGT	R87305	P	Uninj.	NO.	DATE
RENNIE, A.R.	LAC	K253832	NAV	Uninj.	No sig	
MCRAE, J.A.	LAC	R205747	NAV	Uninj.	D 14 (REVISED)	
GRIFFITHS, J.O. GB	LAC	R655425	AB	Uninj.	NO.	CHECKED
BLOOMFIELD, G.L.	SGT	NZ4212630	WO	Uninj.	9	
M.H.F.A.					#14	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Cheetah IX	A173676/AS34402	52	603	SOLO	DUAL	SOLO	DUAL
	A175582/AS30063			1518	63	1556	109

ACCIDENT CLASSIFICATION

TYPE OF A/C
TYPE OF UNIT
CATEGORY

COMMAND
MONTH
STAGE OF FLIGHT
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY

RAF M X

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Navigation and air bombing training.

Cracked #3 cylinder port motor.

NATURE OF ACCIDENT:

While over Griswold bombing range, port motor commenced to run rough with excessive vibration, losing power. Pilot landed at Rivers airport for necessary repairs.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

33. Technical defect.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL