

CASPIR Aircraft Accident Cards

Serial: FP749

Title: Avro Anson Mk. II serial:FP749 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-May-19. Anson II s/n FP749. This accident involved 1 person. Beaman HE

Keywords: RCAFAnson II,FP749,15 SFTS,15 Service Flying Training School,Aerodrome,1944-May-19,BeamanRCAF L20

Created: 1944-05-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP749>

PURPOSE OF FLIGHT:

Solo practice.

NATURE OF ACCIDENT:

Pupil pilot allowed a/c to swing on take-off, taking incorrect remedial action. A/C ground looped, causing u/c to collapse.

CLASSIFICATION:

~~Swinging.~~
12- *Swing*

SECONDARY OR CONTRIBUTORY FACTORS:

~~38~~ *Ground loops*

TECHNICAL OFFICER'S REPORT:

NIL

05/1966/USC

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Log book endorsed and grounded one week.