



PURPOSE OF FLIGHT:

Instrument take-off.

NATURE OF ACCIDENT:

Pupil pilot made a faulty take-off. Instructor endeavoured to correct, but wind dropped and struck ground.

CLASSIFICATION:

11. Hitting obstructions.

SECONDARY OR CONTRIBUTORY FACTORS:

32. Pilot error.

TECHNICAL OFFICER'S REPORT:

NIL

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*11/32*

ACTION TAKEN:

NIL