

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 1 O.T.U. Bagnetville	COM. E	PLACE M.A.	DATE 1-5-44	TIME 1900 GMT
A/C TYPE HURRICANE XIIA		No. 1352	CRASH CAT. "D"	H.Q. FILE 1100-13-52
		S.E. X	M.E.	DAY X
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
BERCH, A.P.	P/O	J41867	P	Uninj.	No. A376	DATE 1-5
					D 14 (REVISED)	
					No. 1	CHECKED <input checked="" type="checkbox"/>
					#1	

MONTH

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL

INI.

INJURY

3RD

RAF

STAGE OF FLIGHT

TYPE OF A/C

TYPE OF UNIT

CATEGORY

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS					
		ON TYPE		TOTAL			
Merlin	19669/A5943 ser.ous	INST.	NIGHT	SOLO	DUAL	SOLO	DUAL
		46	21	53	-	172	142

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

PURPOSE OF FLIGHT:

Cine gun.

TECHNICAL OFFICER'S REPORT:

LUC / UPD

NATURE OF ACCIDENT:

Pilot landed a/c claims wheels down green lights on and horn not blowing. Landing was witnessed and was good. On landing stbd wheel collapsed causing damage to propellor, u/c and wing tip.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~33. Technical defect.~~

5 U/c failure

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL