

CASPIR Aircraft Accident Cards

Serial: 6374

Title: Avro Anson Mk. I serial:6374 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-June-23. Anson I s/n 6374. This accident involved 5 people. Mcbratney JH, McCambley FR, Nicholas MT, Timm OA, West JT

Keywords: RCAFAnson I,6374,5 AOS,5 Air Observer School,Portage La Prairie,1944-June-23,Mcbratney,McCambley,Nicholas,Timm,WestRCAF L20

Created: 1944-06-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6374>

ACCIDENT CLASSIFICATION

UNIT 5 A.O.S.	COM. 2	PLACE Portage la Prairie.	DATE 23-6-44	TIME 2310
Winnipeg, Man.		H.Q. FILE		
A/C TYPE ANSON I	NO. 6374	CRASH CAT. FE	S.E.	M.E. X
		DAY	NIGHT X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
McCambley, F.R.	SGT	R117168	P	Uninj.	NO.	DATE
West, J.T.	LAD	R197957	NAV	Uninj.	D 14 (REVISED)	
McBratney, J.H.	LAC	R255538	NAV	Uninj.		
Timm, O.A.	LAC	R192226	AB	Uninj.	NO.	CHECKED
Nicholas, M.T.	NZ SGT	4216705	WO		#29	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
Cheetah IX	10628/AS31094 Nil.	INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		69	514	1253	110	1283	147

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY

Grid of numbers 1-30 along the top and bottom edges, and letters A-D along the left and right edges, used for accident classification.

PURPOSE OF FLIGHT:

Navigation & Air Bombing Training.

NATURE OF ACCIDENT:

Stbd. motor was running very rough then failed completely in vicinity of Treherne, Man. Pilot landed at Portage la Prairie airport as port motor heated when he tried to maintain altitude on the one engine.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

TECHNICAL OFFICER'S REPORT:

#4 Cylinder stbd. engine exhaust rocker standard broken (Cronic Failure)

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Nil.