

## CASPIR Aircraft Accident Cards

---

**Serial:** FP704

**Title:** Avro Anson Mk. II serial:FP704 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-June-26. Anson II s/n FP704. This accident involved 1 person. Pring CR

**Keywords:** RCAFAnson II,FP704,9 SFTS,9 Service Flying Training School,Crediton,1944-June-26,PringRCAF L20

**Created:** 1944-06-26

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP704>



PURPOSE OF FLIGHT:

11,12,13,17,33.

TECHNICAL OFFICER'S REPORT:

FE/AC/PCODE/ES/PT/PM/I

Complete engine failure.

NATURE OF ACCIDENT:

FB/HOP/PCODE/ES/PT/PM/I

Instructor took off with insufficient fuel in outer tanks and after 20 Min. complete engine failure resulted.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

Tanks were switched to inners and wobble pump used to no avail. F/L was carried out and a/c ran into ditch after landing.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

Pilot logged under A.F.A.O. A.15/5