

CASPIR Aircraft Accident Cards

Serial: 9875

Title: Bristol Bolingbroke Mk. IVT serial:9875 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-June-15. Bolingbroke IVT s/n 9875. This accident involved 2 people. Mackay DR, Morrella TD

Keywords: RCAF Bolingbroke IVT, 9875, 8 BGS, 8 Bomb & Gunnery School, Aerodrome, 1944-June-15, Mackay, Morrella RCAF L20

Created: 1944-06-15

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000258#9875>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

LUC/UTB/USM/CE

Routine Flight.

Port tire failure

LUC/UTB/USM/CE

NATURE OF ACCIDENT:

The a/c was returning from Calgary. Upon landing at No. 8 B.G.S. the port tire was blown out, which caused the a/c to ground loop and catch fire due to the std. u/c folding when the a/c ground looped off the runway. Every effort was made to right the a/c from the ground loop but to no avail.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

37. Tire burst.

ACTION TAKEN:

Nil.