



ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S.
Medicine Hat

COM. 4

PLACE
M.A.

DATE 25-6-44 TIME 0210

H.Q. FILE 1100-27-93

A/C TYPE
HARVARD II
HARVARD II

NO. 2793D
2903

CRASH CAT. "D"
"D"

S.E. X M.E. DAY NIGHT X

COMMAND

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

PETERSON, W.L.

LAC

R221859

PP

Uninj. 2793

NO. A121

DATE 26-6

DE SMETT, M.J.J.

LAC

R814866

PP

Uninj. 2903

A122

26-6

D 14 (REVISED)

NO. 17
18

CHECKED

X

#54

MONTH

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL

INI.

INJURY

3rd

RAF

MZ

STAGE OF FLIGHT

TYPE OF A/C

TYPE OF UNIT

CATEGORY

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Wasp S3HI

262253/13088 slight
4389/8530 Nil

INST.

NIGHT

ON TYPE

TOTAL

SOLO

DUAL

SOLO

DUAL

-

12

30

56

64

95

-

12

35

52

75

92

ACCIDENT CLASSIFICATION



PURPOSE OF FLIGHT:

Solo night flying circuits and landings.

TECHNICAL OFFICER'S REPORT:

MULT

NATURE OF ACCIDENT:

While waiting at taxiing post with navigation and upper identification lights on, this a/c (2903) was taxi'd into from behind by a/c 2793.

NIL
TCA/PCT ✓
TCA/XA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pilot of A/C 2793 awarded 7 days extra work cleaning a/c.
Pilot of A/C 2903 awarded 7 days extra work cleaning a/c.