

ACCIDENT CLASSIFICATION

UNIT 1 <b>S.F.T.S.</b> Camp Borden		COM. 1	PLACE Edenvale, Ont.		DATE 29-6-44	TIME 1015	
A/C TYPE HARVARD IIB HARVARD IIB		NO. FE759 D FE433	CRASH CAT. "D" $\frac{1}{4}$ "D" $\frac{1}{2}$	S.E. X X	M.E.	DAY X NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		
BORTHWICK, N.W.		LAC	R223327	PP	Uninj.		
JEWITT, E.T.		LAC	R203415	PP	Uninj.		
					SIGNAL		
					NO. C664	DATE 30-6	
					D 14 (REVISED)		
					NO. 7	CHECKED <input checked="" type="checkbox"/>	
					#70		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS			
Wasp		41-12346/13823 Nil 42-763/15899 Nil		ON TYPE		TOTAL	
				INST.	NIGHT	SOLO	DUAL
				34	21	49	78
				27	23	51	70
						69	118
						75	107

ACCIDENT CLASSIFICATION

COMMAND  
 MONTH  
 STAGE OF FLIGHT

FORCED LANDING  
 TAXIING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STATRY  
 FATAL  
 INJ.  
 INJURY  
 3RD  
 5

7  
 4  
 2  
 1  
 7  
 4  
 2  
 1

RAF M 2

PURPOSE OF FLIGHT:

3 plane formation.

NATURE OF ACCIDENT:

On changing to echelon port from VIC formation a/c FE759 collided with a/c FE433.

TECHNICAL OFFICER'S REPORT:

NIL

ICA/PCLV

ICA/KA

MULT

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

21. Collisions a/c

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed "Error in judgment" of pilot of a/c FE759