

ACCIDENT CLASSIFICATION

UNIT 1 O.T.U.
Bagotville

COM.
E

PLACE
M.A.

DATE 21-6-44 TIME 1615

H.Q. FILE 1300-V7402

A/C TYPE
HURRICANE XIIIA

NO.
V7402

CRASH CAT.
"D"

S.E. X M.E. DAY X NIGHT

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

ROBINSON, B.J.C. GB

SGT

1803116

P

Uninj.

NO.
A79

DATE
21-6

D 14 (REVISED)

NO.
4

CHECKED

#5

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Packard Merlin 19293/A495

INST.

NIGHT

ON TYPE

TOTAL

41

27

27

SOLO

27

DUAL

-

SOLO

165

DUAL

151

ACCIDENT CLASSIFICATION

COMMAND

MONTH


STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
9rd
5

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Cine gun.

TECHNICAL OFFICER'S REPORT:

LUC/UDM/XFM
NIL / LUC/UDH

NATURE OF ACCIDENT:

Pilot made wheels up landing, after failing to get wheels down causing damage to propeller, airframe and possibly to engine.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

5. U/C failure.

SECONDARY OR CONTRIBUTORY FACTORS:

35. U/C defect.

Control panel found missing from hydraulic selector box.

ACTION TAKEN:

Charge laid against responsible airman.