

ACCIDENT CLASSIFICATION

UNIT 1 O.T.U. Bagotville	COM. E	PLACE M.A.	DATE 22-6-44	TIME 1505 GMT
A/G TYPE HURRICANE XII		NO. 5696	CRASH CAT. "D"	H.Q. FILE 1100-56-96
		S.E. X	M.E.	DAY X
		NIGHT		


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
HEYDON, K.T. AUS	P/O	429193	P	Uninj.	NO. A80	DATE 22-6
					D 14 (REVISED)	
					NO. 5	CHECKED <input checked="" type="checkbox"/>
					#6	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
Packard Merlin AC4147704/A3547		37	20	31	-	129	138

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
9FD
5



PURPOSE OF FLIGHT:

Formation flying.

NATURE OF ACCIDENT:

Pilot reports engine cutting out and did not select wheels down.

TECHNICAL OFFICER'S REPORT:

NIL

LUC / PCDF / UCDL

u/c FOUND SERVICEABLE SUFFICIENT FUEL IN TANKS

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

Pending investigation