

ACCIDENT CLASSIFICATION

UNIT # 7 A.O.S.	COM. 2	PLACE Virden airport.	DATE 14-7-44 TIME 0130
A/C TYPE ANSON I		NO. 6984	H.Q. FILE 1100-69-84
		CRASH CAT. NEW Engine	S.E. M.E. DAY NIGHT
			X X

COMMAND

PERSONNEL	RANK	NUMBER	DUTY.	INJURIES	SIGNAL	
Bernreiter, M.	Sgt	R181893	P	Nil	No Sig.	DATE
Walmsley, H.W.	Sgt	R192552	CoP	Nil		
St Arnaud, R.I.O.	LAC	K265912	1 Nav	Nil	D 14 (REVISED)	
Goertzen, V.A.	LAC	R281920	2 Nav	Nil	No.	CHECKED
Baillie, J.	WFF	R197623	WOP	Nil	9	
					# 17	

MONTH

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Cheetah IX	A10819/AS31401 A10974/AS31515	61	114	132	384	172	419

STAGE OF FLIGHT

ACCIDENT CLASSIFICATION

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL

INJ.

3RD

5

M

PURPOSE OF FLIGHT:

Navigation exercise.

TECHNICAL OFFICER'S REPORT:

Engine failure.

SFE/ET/NK/NK/I

NATURE OF ACCIDENT:

Stbd motor failed, necessitating landing at Virden. C.A.V.U. No moon.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

18. Misc. Technical.

SECONDARY OR CONTRIBUTORY FACTORS:

27. Engine trouble-No Damage.

ACTION TAKEN:

Nil