

CASPIR Aircraft Accident Cards

Serial: FP731

Title: Avro Anson Mk. II serial:FP731 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-July-21. Anson II s/n FP731. This accident involved 1 person. Cook RC

Keywords: RCAFAnson II,FP731,7 SFTS,7 Service Flying Training School,Calgary,1944-July-21,CookRCAF L20

Created: 1944-07-21

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP731>

ACCIDENT CLASSIFICATION

UNIT 7 S.F.T.S.
Macleod, Alta.

COM.
4

PLACE
Y.C. Calgary.

DATE 21-7-44 TIME 1530

H.Q. FILE 1330-FP731

A/C TYPE
ANSON II

No.
FP 731

CRASH CAT.
~~FP~~ D

S.E. M.E. DAY NIGHT
X X

COMMAND

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

Cook, R.C.

AUS

WO1

404400

PP

Uninj.

No. DATE
A259 22-7

D 14 (REVISED)

No. CHECKED
✓

#38

MONTH

STAGE OF FLIGHT

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Jacobs L6MB

17209/3388 Slight
26324/14810

INST.

NIGHT

ON TYPE

TOTAL

DUAL SOLO

DUAL SOLO

36

27

94

76

124

107

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL INJ. 3RD

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Advanced Nav. exercise

NATURE OF ACCIDENT:

Cylinder blown off causing F/L*

TECHNICAL OFFICER'S REPORT:

Cylinder Barrel failure in air.

FB/ET/MP/D/I

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

27. Engine trouble - no damage

ACTION TAKEN:

Nil.