

PURPOSE OF FLIGHT:

Instruction on Seq.

NATURE OF ACCIDENT:

After Landing, a/c swung to stbd.
Pilot failed to stop swing and a/c
ground-looped.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

Nil.

LS/PSS LS/PSS/USS

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Pilots Log Book endorsed "Carelessness.."