

61
60
59
58
57
56
55
54
53
52
51
50
49
48
47
46
45
44
43
42
41
40
39
38
37
36
35
34
33
32
31

ACCIDENT CLASSIFICATION

UNIT 11 S.F.T.S. Yorkton, Sask.	COM. 2	PLACE M.A.	DATE 19-7-44	TIME 0850
A/C TYPE CRANE I CRANE I			H.Q. FILE 1100-80-34	
No. 8745 -D 8034		CRASH CAT. "D" "D"	S.E.	M.E. X
			DAY X	NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
A/C8745 Glenn, J.T.	LAC	R214297	P	Uninj.	NO.	DATE
Pearce, G.L.	LAC	R220697	PP	Uninj.	A49	19-7
A/C8034 MacIise, H.J.	F/O	J37046	F.I.	Uninj.	D 14 (REVISED)	
Howett, A.W.	LAC	R118435	P.P.	Uninj.	NO.	CHECKER
Vane, R.T.	GB LAC	1809968	Pass	Uninj.	#8	

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Jacobs LAMB	P.22002/4753 Nil.						
	S21632/4486 Nil						
Jacobs LAMB	P.21893/4796 Nil	45	25	102	70	138	110
	S.22209/8273 Nil	39	24	99	69	138	105
		82	24	145	431	212	484
		43	23	99	472	178	108
		41	25	100	64	147	106

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAIRY
FATAL
INJ.
3rd
INJURY

ACCIDENT CLASSIFICATION

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
RAF
M

PURPOSE OF FLIGHT:

Squadron formation Exercise.

TECHNICAL OFFICER'S REPORT:

Nil.

MULTI

8745 TCA/PCT

TCA/PCT

8034 TCA/XA

TCA/XA

NATURE OF ACCIDENT:

Crane 8745 Taxied propellers into rudder and elevators of Crane 8034.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Review of ...