

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE N.I.	DATE 4-7-44	TIME 0815
A/C TYPE HARVARD II		NO. A3954	CRASH CAT. "B"	H.Q. FILE 1300-A3954
		S.E. X	M.E.	DAY X
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
CARTER, A.S.	F/O	136465	FI	Uninj.	NO. A172	DATE A-7
SMITH, D.S.	F/	51815	FP	Uninj.	D 14 (REVISED)	
					NO. 2	CHECKED <input checked="" type="checkbox"/>
					11	

MONTH

STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATUTORY
FATAL
INJ
3RD
INJURY
5
4

TYPE OF A/C
TYPE OF UNIT
CATEGORY
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
RAF
W

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PURPOSE OF FLIGHT:

Essential dual exercise.

TECHNICAL OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT:

Pupil was practicing precautionary landings and instructor failed to take over in time to prevent a/c from stalling from a height of 25ft.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LH/PSHH/1/USH ✓

CLASSIFICATION:

4. Heavy.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed.