

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S Medicine Hat	COM. 4	PLACE M.A.	DATE 6-7-44	TIME 1155
A/C TYPE HARVARD IIB		NO. FE453	CRASH CAT. "D"	H.Q. FILE 1300-FE453
		S.E. X	M.E. 	DAY X
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
HERRBURN, J.	F/O	51384	PP	Uninj.	NO. A173	DATE
					D 14 (REVISED)	
					NO. 3	CHECKED
					#10	


MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Boeing R1340/AnI	4210016/22408 Ni	-	-	129	81	174	114

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY
3RD
S

ACCIDENT CLASSIFICATION



PURPOSE OF FLIGHT:

Solo exercises - 13 (i) 13 (111) 22,25.

TECHNICAL OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT:

Ground loop on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LS/PSS/USS ✓

CLASSIFICATION:

7. Others.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL