

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 2 W.S. Calgary, Alta.	COM. 4	PLACE Shepard, Alta.	DATE 9-7-44	TIME 1025
A/C TYPE HARVARD II	NO. 2750	CRASH CAT. "E"	S.E. X	M.E. DAY X NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Howard, R.C.	P/O	J39426	P	Uninj.	NO.	DATE
Sills, G.A.	LAC	R276488	WC	Uninj.	D 14 (REVISED)	
					NO.	CHECKED
					#39	

MONTH  
FORCED LANDING  
TAXIING  
LANDING  
STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
P&W S3H1	4343/8484 Nil.	35	20	90	300	120	330

FLIGHT  
STAIRY  
FATAL  
INJ.  
INJURY 3RD

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

PURPOSE OF FLIGHT:

W/T Exercise.

NATURE OF ACCIDENT:

Ground-looped after landing, damaging port wing tip.

TECHNICAL OFFICER'S REPORT:

Nil.

LS/PSS

LS/PSS ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pilot logged.