

## CASPIR Aircraft Accident Cards

---

**Serial:** 2894

**Title:** North American Harvard Mk.II serial:2894 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1944-July-18. Harvard II s/n 2894. This accident involved 1 person. McCarthy J

**Keywords:** RAFHarvard II,2894,34 SFTS,34 Service Flying Training School,Aerodrome,1944-July-18,McCarthyRCAF L20

**Created:** 1944-07-18

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2894>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.C. Medicine Hat	COM. 4	PLACE M.I.	DATE 18-7-44	TIME 1100
A/C TYPE HARVARD II		NO. 2894	CRASH CAT. "5"	H.Q. FILE 1100-28-94
		S.E. X	M.E.	DAY X
				NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
MCCARTHY, J.	LAC	1814654	PF	Uninj.	NO.	DATE
					No sig	
					D 14 (REVISED)	
					NO.	CHECKED
					15	<input checked="" type="checkbox"/>
					#67	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Yasp S3HI	262288/13123 Nil	-	-	78	37	125	77

TYPE OF A/C	TYPE OF UNIT	CATEGORY	COMMAND	MONTH	STAGE OF FLIGHT	FORCED LANDING
						TAXIING
						LANDING
						TAKE-OFF
						FLIGHT
						STATRY
						FATAL
						INJ.
						3RD
						S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Solo exercises.

NATURE OF ACCIDENT:

Pupil pilot bounced badly on landing and wing dropped and struck ground.

TECHNICAL OFFICER'S REPORT:

NIL

LH/PSHL

LH/PSHL ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

4. Heavy.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed.