

CASPIR Aircraft Accident Cards

Serial: FE874

Title: North American Harvard Mk. IIB serial:FE874 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-July-19. Harvard IIB s/n FE874. This accident involved 1 person. Cawley KR

Keywords: RAFHarvard IIB,FE874,34 SFTS,34 Service Flying Training School,Dunmore,1944-July-19,CawleyRCAF L20

Created: 1944-07-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE874>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Elementary formation.

NATURE OF ACCIDENT:

NIL

Forced landing due to violent vibration of a/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

FB/AOP/ET/PR/D/IV

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

fatigue fracture of one propeller blade
39. Structural failure. resulted
in severe vibration + loosening of engine cowling.

NIL