

## CASPIR Aircraft Accident Cards

---

**Serial:** 8247

**Title:** Avro Anson Mk. II serial:8247 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-August-02. Anson II s/n 8247. This accident involved 2 people. Bradford JC, Lyman MF

**Keywords:** RCAFAnson II,8247,7 SFTS,7 Service Flying Training School,Woodhouse Alberta,1944-August-02,Bradford,LymanRCAF L20

**Created:** 1944-08-02

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8247>

ACCIDENT CLASSIFICATION

UNIT 7 S.I.F.S. MacLeod, Alta.		COM. 4	PLACE Woodhouse, Alta.		DATE 2-8-44	TIME 0840		
A/C TYPE ALSON II		NO. 8247	CRASH CAT. <del>1</del> 5		S.E.	M.E. X	DAY X	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Bradford, J.G.	E/C	J41243	FI	Uninj.	NO.	DATE
Lyman, M.F.	LAC	R211949	FP	Uninj.		
					D 14 (REVISED)	
					NO.	CHECKED
					#13	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Jacobs 16MB	4247/17069 Serbauch 10086/26832 Nil	48	42	104	112	154	284
		24	21	67	41	111	85

ACCIDENT CLASSIFICATION

COMMAND  
MONTH  
STAGE OF FLIGHT

Forced Landing  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STRATRY  
FATAL  
INJURY

3RD  
5  
M

PURPOSE OF FLIGHT:

Navigation Cross Country.

TECHNICAL OFFICER'S REPORT:

Port engine failed.

NATURE OF ACCIDENT:

Failure of port engine due to broken crankshaft.

*FB/ET/AM/D/I*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - Accident.

ACTION TAKEN:

Nil