

CASPIR Aircraft Accident Cards

Serial: 8227

Title: Avro Anson Mk. II serial:8227 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-August-19. Anson II s/n 8227. This accident involved 3 people. D'albenas EW, Smith H, Whitely J

Keywords: RCAFAnson II,8227,6 BGS,6 Bomb & Gunnery School,Aerodrome,1944-August-19,D'albenas,Smith,WhitelyRCAF L20

Created: 1944-08-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8227>

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 6 B.G.S.. Mountain View COM. 1 PLACE M.A. DATE 19-8-44 TIME 0040 H.Q. FILE 1100-82-27

A/C TYPE ANSON II NO. 8227 CRASH CAT. "D" S.E. M.E. DAY NIGHT X X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
D'ALBEMAS, E.W.	P/O	J42020	F	Uninj.	NO.	DATE
SMITH, H.	CB	LAC 1476764	OC	Uninj.	D 14 (REVISED)	
WHITELY, J.	CB	LAC 1625562	OC	Uninj.	NO. 2	CHECKED <input checked="" type="checkbox"/>
					#35	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Jacobs LohB	16907/3086 Mil	47	31	DUAL	SOLO	DUAL	SOLO
	15589/1777 Mil			21	239	142	399

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE OFF
FLIGHT
STRATY
FATAL
INI.
INJURY
3RD
5

PURPOSE OF FLIGHT:

Night bombing exercises.

TECHNICAL OFFICER'S REPORT:

Stbd propeller (Hoover) both blades broken. Defective port master brake cylinder.

NATURE OF ACCIDENT:

A/C collided with taxi post due to failure of port brake, damaging stbd propeller.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TCO/UBF

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

36. Brake failure.

ACTION TAKEN:

NIL