



PURPOSE OF FLIGHT:

Night bombing exercises.

TECHNICAL OFFICER'S REPORT:

Stbd propeller (Hoover) both blades broken. Defective port master brake cylinder.

NATURE OF ACCIDENT:

A/C collided with taxi post due to failure of port brake, damaging stbd propeller.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TCO/UBF

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

36. Brake failure.

ACTION TAKEN:

NIL