



PURPOSE OF FLIGHT:

Gunnery Exercise.

NATURE OF ACCIDENT:

Taxiing accident. Boly. collided with  
two parked Ansons. Downwind, downhill  
with w/a brakes, toward parked a/c. Another  
Anson, taxiing immediately in front of  
Boly, turned right, then changed and  
turned left, preventing Boly. pilot  
from turning left as intended. Brakes  
failed after application on landing  
run and long crosswind taxiing.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

36. Brake failure.

TECHNICAL OFFICER'S REPORT:

Brakes rendered inoperative due to heating resulting  
in glazed brake blocks.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY NO.

TCA/UBF  
MA/XA  
MA/XA

ACTION TAKEN:

Log Book Endorsed