

ACCIDENT CLASSIFICATION

UNIT # 3 B.G.S. MacDonald	COM. 2	PLACE 20 miles E. of M.A.	DATE 29-8-44	TIME 1125
A/C TYPE Bolingbroke IVT Bolingbroke IVT		NO. 10222 -D 10165	CRASH CAT. "E"	H.Q. FILE 1100-101-65
		S.E.	M.E.	DAY X
				NIGHT X


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Slater, E.A.	WO2	R145406	P	Nil	NO. N27	DATE 30-8
Harry, V.N.	Sgt	R120163	AG1	Nil		
Warner, R.A.	LACR	267396	AG	Nil		
Walker, G.	LAC	R147116	AG	Nil	D 14 (REVISED)	
Walker, E.W.	NZ LAC	4214231	AG	Nil	NO. 5	CHECKED
Hayman, W.D.	F/S	168302	P	Nil		
Tennant, J.E.	LAC	R289490	AG	Nil	# 13	
Swadden, J.F.	LAC	R289358	AG	Nil		
Smith, J.A.	LACR	294526	AG	Nil		

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Mercury XX	12664/52964	49	15	4	332	132	1106
	12541/250022						
	12146/57130						
	12032/56722						
		46	23	10	212	128	691

ACCIDENT CLASSIFICATION

COMMAND
 MONTH
 STAGE OF FLIGHT

FORCED LANDING
 TAYING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJURY



PURPOSE OF FLIGHT:

Camera gun exercise.

NATURE OF ACCIDENT:

Flying formation on exercise, port engine failed causing a/c 10222 to swing to left scraping port wing over stbd tailplane on a/c 10165, slightly damaging tailplane.

CLASSIFICATION:

21. Collisions a/c.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

MULT
Momentary engine failure.

ICA/PSF/FE/ET/NK/1
ICA/KA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Summary of evidence;