

ACCIDENT CLASSIFICATION

UNIT 1 S.F.T.S. Camp Borden.	COM. 1	PLACE Sunnidale Road near Creemore	DATE 1-8-44	TIME 1600			
	A/C TYPE HARVARD II	NO. 3339	CRASH CAT. "D"2	FILE NO. 1100-33-39			
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Millard, J.M.		LAC	R201352	P	Uninj.	NO. C6 73/3-8	DATE
						D 14 (REVISED)	
						NO.	CHECKED
						#7	
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
	5099/11329		INST.	NIGHT	ON TYPE		TOTAL
					DUAL	SOLO	DUAL SOLO

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
3RD
INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Solo Seq. Practice.

TECHNICAL OFFICER'S REPORT:

N11

FB/AOP/ES/NK/11/UDK/B ✓

NATURE OF ACCIDENT:

Engine failed in flight. Pupil did wheels up forced landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

11481

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident

ACTION TAKEN:

N11