

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 1 S.F.T.S. Camp Borden	COM. 1	PLACE 2 miles N of Minesing,	DATE 9-8-44	TIME 1100
A/C TYPE HARVARD II	No. 2644	CRASH CAT. "A"	S.E. X	M.E. DAY X
			H.Q. FILE 1100-26-44	NIGHT

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
FATAL
INJ.
INJURY

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
LOCKETT, K.A.	LAC	R255279	PP	Uninj.	NO.	DATE
					D 14 (REVISED)	
					NO.	CHECKED
						#23

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Wasp	4577/9018 total	22	16	70	47	129	76

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF

PURPOSE OF FLIGHT:

Solo seq³

NATURE OF ACCIDENT:

While doing aerobatics, stalled on top of loop flicked into spin to right attempted to recover but a/c continued to spin. Adandoned a/c at 300'.

TECHNICAL OFFICER'S REPORT:

10C/P/AOC/PSF/B/N ✓
NIL

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

19. Out of control.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL