

PURPOSE OF FLIGHT:

Taxying.

TECHNICAL OFFICER'S REPORT:

MULT

MIL.

TCA/PCT ✓
TCA/XA

NATURE OF ACCIDENT:

A/C No. 2796 was being taxied along the perimeter track towards the take off point, when it struck the stbd. wing of No. 818, which was stationary

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collision.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log Book Endorsed "Gross Carelessness."