

CASPIR Aircraft Accident Cards

Serial: 2801

Title: North American Harvard Mk.II serial:2801 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-August-31. Harvard II s/n 2801. This accident involved 1 person. Bortnowski AJ

Keywords: RAFHarvard II,2801,34 SFTS,34 Service Flying Training School,Aerodrome,1944-August-31,BortnowskiRCAF L20

Created: 1944-08-31

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2801>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat		COM. 4	PLACE M.A.		DATE 31-8-44	TIME 0015	
A/C TYPE HARVARD II		No. 2801	CRASH CAT. "D"		H.Q. FILE 1100-28-01		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL
BORTNOWSKI, A.J.		LAC	709567	PP	Uninj.		No. DATE
							D 14 (REVISED)
							No. CHECKED
							#81
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
Wasp S3HI	8392/4251		INST.	NIGHT	ON TYPE		TOTAL
					DUAL	SOLO	DUAL SOLO
			29	15	71	66	125 104

ACCIDENT CLASSIFICATION


COMMAND
 MONTH
 STAGE OF FLIGHT

FORCED LANDING
 TAXIING
 LANDING
 TAKEOFF
 FLIGHT
 STAT'RY
 FATAL
 INJ.
 3RD
 SECURITY
 5

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Night flying circuits and landings.

NATURE OF ACCIDENT:

This a/c made a normal landing, after which a violent swing to right developed, causing damage to the a/c.

TECHNICAL OFFICER'S REPORT:

NIL

LS/PSS ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Swing.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL