

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																				
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																				
PILOT																	OTHERS																	AIRFRAME FAILURE																	ENGINE FAILURE																
CAUSES OF ACCIDENTS																																																																			
UNIT 32 S.F.T.S.										COM.					PLACE					DATE 31-8-44							ME 2110																																								
Moose Jaw										4					M.A.					H.O. FILE 1300-T1177																																															
A/C TYPE OXFORD II										No. T1177					CRASH CAT. NIL					SE			ME X			DAY			NIGHT X																																						
NAME										RANK			No.		DUTY			INJURIES							SERIOUS																																										
ROBERTS, F.										F/O			153679		FI			Slightly Inj.							FATAL			INJURY																																							
MCLAREN, P.R.										F/O			142216		PP			Uninj.																																																	
																									CARD SERIAL No.																																										
																									#12																																										
TYPE A/F & ENGINE			No.			EXTENT OF DAMAGE			REPORT FORM			SERIAL No.			DATE			HOURS FLOWN BY PILOTS																																																	
Cheetah			PRC1294/A172341			Nil									INST.		NIGHT		ON TYPE				TOTAL				LAST 6 MOS.																																								
			RAS41003/A178927												69		113		79		561		181		665																																										
															44		25		113		80		161		117																																										
SIGNAL No. & DATE					UNIT No. & DATE					COM. No. & DATE					REPORT					FILE					DATE																																										
NATURE OF ACCIDENT																																																																			

N.A.F.A.

CAUSES

STAGE OF FLIGHT

- 19 ( )
- 18 ( )
- 17 ( )
- 16 ( )
- 15 ( )
- 14 ( )
- 13 ( )
- 12 ( )
- 11 ( )
- 10 ( )
- 9 ( )
- 8 ( )
- 7 ( )
- 6 ( )
- 5 ( )
- 4 ( )
- 3 ( )
- 2 ( )
- 1 ( )
- 19 ( )
- 18 ( )
- 17 ( )
- 16 ( )
- 15 ( )
- 14 ( )
- 13 ( )
- 12 ( )
- 11 ( )
- 10 ( )
- 9 ( )
- 8 ( )
- 7 ( )
- 6 ( )
- 5 ( )
- 4 ( )
- 3 ( )
- 2 ( )
- 1 ( )
- 19 ( )
- 18 ( )
- 17 ( )
- 16 ( )
- 15 ( )
- 14 ( )
- 13 ( )
- 12 ( )
- 11 ( )
- 10 ( )
- 9 ( )
- 8 ( )
- 7 ( )
- 6 ( )
- 5 ( )
- 4 ( )
- 3 ( )
- 2 ( )
- 1 ( )

DUTY ON WHICH ENGAGED:

Routine night flying training flight

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NIL

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

It appears that F/O Roberts jumped out of a/c while it was taxiing

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

11. Others.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

*Investigation*

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

41. Disobedience of Orders.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_