

CASPIR ARCHIVAL METADATA

Serial:	12072
Title:	Avro Anson Mk. V serial:12072 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1944-September-27. Anson V s/n 12072. This accident involved 5 people. Burley GCH, Crain IJ, Florence DB, Howarth RM, Roper GB
Keywords:	RCAFAnson V,12072,5 AOS,5 Air Observer School,St James Manitoba,1944-September-27,Burley,Crain,Florence,Howarth,RoperRCAF L20
Created:	1944-09-27
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#12072

PURPOSE OF FLIGHT:

Navigation Flight.

TECHNICAL OFFICER'S REPORT:

Failure of inner Stbd. hub fitting.

NATURE OF ACCIDENT:

Upon landing, pilot could not control a/c as each time he applied brakes, a/c shuddered and therefore, he allowed it to continue off the runway and the right u/c collapsed, presumably caused by a defective inner stbd. hub fitting.

FINDINGS:

LUC/UDM

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

SUMMARY No.

CLASSIFICATION:

5. U/C Failure.

SECONDARY OR CONTRIBUTORY FACTORS:

35. U/C Defect.

ACTION TAKEN:

Nil.