

RFOSE OF FLIGHT:	TECHNICAL OFFICER	S REPORT:	
No. 2 cross country flight.	The state of the s	AND ROBERTS OF	*.
TURE OF ACCIDENT:		The state of the s	
After starting his engine the	• pilot COURT OF INCLURY O	4) 24 4	
many and or arrests of TA SERVIT	ERG FINDINGS.	SUMMARY NO.	ORT:
ames inside cowling. He the	on AA		
ire extinguisher. Two airm	en /7/	1/GE TO THE STATE OF THE STATE	
tho were standing by also use		A DESCRIPTION OF AND A SECOND OF	
heir extinguishers. The fir	re tender		
then arrived and the fire was	s put out.		
ASSIFICATION:			- 1
ASSIFICATION:			
4. 2245			
CONDARY OR CONTRIBUTORY FAC	TORS:	2	
CONDARY OR CONTRIBUTORY FAC	TORS:	2	
CONDARY OR CONTRIBUTORY FAC	ACTION TAKEN:	2	
CONDARY OR CONTRIBUTORY FAC		2	