

ACCIDENT CLASSIFICATION

UNIT **34 S.F.T.S.
Medicine Hat**

COM. **4**

PLACE **M.A.**

DATE **25-9-44** TIME **1350**

H.Q. FILE **1100-32-74**

A/C TYPE

HARVARD II

NO.

3274

CRASH CAT.

"D"

S.E.

X

M.E.

X

DAY

NIGHT

COMMAND

MONTH

STAGE OF FLIGHT

PERSONNEL

BAILEY, R.A.

RANK

LAC

NUMBER

1632219

DUTY

PP

INJURIES

Uninj.

SIGNAL

NO.

Lettergram

DATE

D 14 (REVISED)

NO.

6

CHECKED

#37

FORCED LANDING
TAXIING
LANDING
TAKE OFF
FLIGHT
STATRY
FATAL
INJ
INJURY
3RD
RAF
W K

ENGINE

Wasp S3HI

ENGINE NUMBER (S)

13113/262278 slight

HOURS FLOWN BY PILOTS

INST.

-

NIGHT

-

ON TYPE

87

DUAL

76

TOTAL

130

DUAL

106

TYPE OF A/C

TYPE OF UNIT

CATEGORY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Air to ground firing practice.

NATURE OF ACCIDENT:

This a/c made a normal stalled landing and then swung violently to stbd, causing slight damage to the a/c.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

NIL LS/PSS ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

NIL