



PURPOSE OF FLIGHT:

Test on new engine.

TECHNICAL OFFICER'S REPORT:

Broken blade red bolt indicated.

NATURE OF ACCIDENT:

Pilot made wheels up landing on field, forced landing, broken connecting rod.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

FB/AOP/ES/IM/D/I/UOK/B

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

NIL