

ACCIDENT CLASSIFICATION									
UNIT # 6 O.T.U.		COM. WAC		PLACE Tofino Aerodrome		DATE 28-9-44 TIME 1550			
A/C TYPE EXPEDITOR I		No. R985		CRASH CAT. "D"		S.E.	M.E.	DAY	NIGHT
							X	X	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Maloney, J.M.		F/O	132782	PP	Nil		No.	DATE	
Coles, H.J.		F/O	J23449	PP	Nil		A478	20-10	
							D 14 (REVISED)		
							No.	CHECKED	
							# 1		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Jacobs		42/23125		INST.		ON TYPE		TOTAL	
		42/23126		NIGHT					
				DUAL	SOLO	DUAL	SOLO		
				125	161	17	39	192	1430
				36	54	15	41	105	716
ACCIDENT CLASSIFICATION									

PURPOSE OF FLIGHT:

Radio Range exercise involving a landing at Tofino B.V.

NATURE OF ACCIDENT:

While turning a/c to park, pilot misjudged his radius of turn and touched a parked truck with wing tip. Attenuating circumstances are, inexperience of pilot on type and the fact that the truck was parked in the wrong place and very difficult to see.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

Nil

TCO/PCT/XOV/XCA ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY NO.

Remarks of Unit C.O.

Truck parked in unsuitable place. Color of truck made it difficult to see.

ACTION TAKEN:

Log; Book endorsed.