

ACCIDENT CLASSIFICATION

UNIT 2 W.S., Flying Sqdn. Shepard, Alta	COM. 4	PLACE No.2 W.S. Shepard, Alta.	DATE 14-10-44	TIME 10.30
A/C TYPE HARVARD IIA	NO. AJ791	CRASH CAT. Nil	S.E. X	M.E.
			DAY X	NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
CHESTER	P/O	J46933	P.P.	Uninj.	No Sig.	DATE
FUNK	LAC		P.P.	Uninj.		
LEE	Sgt.	R19836	P.P.	Uninj.		
MacRAE	LAC		P.P.	Slightly Injured	D 14 (REVISED)	
					NO.	CHECKED
					2	
					20	

MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO

INJURY

ACCIDENT CLASSIFICATION

NI AFA

PURPOSE OF FLIGHT:

W.A.G. Ex.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT: Sgt. Lee with his

trainee LAC MacRae were walking across tarmac, talking, when a/c AJ791 piloted by P/O Chester was taxiing out of line.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Neither Sgt. Lee nor LAC MacRae saw approaching a/c, and as P/O Chester was watching for parked a/c, he did not see either Sgt. Lee or LAC MacRae until upon them. Pilot of AJ791 took action immediately he saw them, but port wing struck LAC MacRae.

CLASSIFICATION:

11. Others.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil