

CASPIR Aircraft Accident Cards

Serial: 8288

Title: Avro Anson Mk. II serial:8288 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1944-November-18. They are: Anson II s/n FP933, Anson II s/n 8288. This accident involved 3 people. Broun HH, Edmonds RC, Wohlers LA

Keywords: RCAFAnson II,8288,15 SFTS,15 Service Flying Training School,Aerodrome,1944-November-18,Broun,Edmonds,WohlersRCAF L20

Created: 1944-11-18

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8288>

ACCIDENT CLASSIFICATION

UNo. 15 S.F.T.S.

COM 4

PLACE M.A.

DATE 18-11-44

TIME 14.45

H.Q. FILE 1300-FP933

A/C TYPE ANSON II
ANSON II

NO. FP933-D
8288

CRASH CAT. **WDM**
WCM

S.E. M.E. DAY NIGHT
X X

COMMAND

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

WOHLERS, L.A., AUS
EDMONDS, R.C.,
BROUN, H.H., AUS

LAC
F/L
LAC

438634
J7341
439947

P.P.
F.I.
P.P.

Uninj.
Uninj.
Uninj.

NO. DATE
18-11

D 14 (REVISED)

NO. CHECKED
3

9

MONTH

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STABILITY

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Jacobs P26862/10116 Nil
L6MB S16734/2913
P25291/9661 Nil
S25125/9495

INST.

NIGHT

ON TYPE

TOTAL

DUAL

SOLO

DUAL

SOLO

7
99
17

7
165
7

5
93
8

1
820
2

46
166
53

44
1634
37

STAGE OF FLIGHT

INJ. 3rd
INJURY 5th
RAF 1st

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Solo practice on Circuits &
Landings.

TECHNICAL OFFICER'S REPORT:

N11

TCA/PCT

TCA/XA

MULT.

NATURE OF ACCIDENT:

L A Cwehlers, in charge of FP933
turned cross wind after landing, and
FP933 collided with 8288 in the charge
of F/L Edmonds which was parked between
the inner and outer runways, while LAC
Broun carried out his after landing check.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Endorsement of log book.