

ACCIDENT CLASSIFICATION

<b>Wt. 9 B &amp; G S</b> <b>Mont Joli, P.Q.</b>	COM.	PLACE	DATE	TIME
	3	Station Aerodrome Mont Joli, P.Q.	18-11-44	1000
A/C TYPE	No.	CRASH CAT.	H.Q. FILE	
BATTLE	2129	"B"	1100-21-29	
		S.E.	M.E.	DAY NIGHT
		X		X


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
VANASSE, J.G.R.	P/O	J44546	P	Slightly Inj.	NO.	DATE
KMICIK, E.C.	LAC	R278899	AG/UT	Uninj.	N111	18-11
SMITHERS, J.K.P.,	LAC	R290704	AG/UT	Uninj.	D 14 (REVISED)	
					NO.	CHECKED
					4	
					4	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Merlin III	148091/14297 Serious	43	21	3	185	129	285

ACCIDENT CLASSIFICATION

COMMAND  
 MONTH  
 STAGE OF FLIGHT

FORCED LANDING  
 TAXIING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STATRY  
 FATAL  
 INJ.  
 INJURY 3rd  
 INJURY 5th  
 INJURY 1st



PURPOSE OF FLIGHT:

Scheduled Gunnery Ex.,

TECHNICAL OFFICER'S REPORT:

No. 6 connecting rod thrown through sidewall of engine.

NATURE OF ACCIDENT:

Engine seized and caught fire in aerodrome circuit. Pilot, being burned about face could not see and forced landed wheels retracted, on station aerodrome; fire being extinguished by crash crew .

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LB/AOP/PM/ES/IM/NK/IL/UNIT/AE

CLASSIFICATION:

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

ACTION TAKEN:

Nil