

TYPE OF A/C		ACCIDENT CLASSIFICATION										DATE 18-11-44 TIME 1715				COMMAND
UNIT 9 B & G S Mont Joli, P.Q.		COM. 3	PLACE 1 mile East of Matane P.Q.				H.Q. FILE 1100-74-41									
A/C TYPE BATTLE		NO. 7441		CRASH CAT. "A"		S.E. X	M.E.	DAY X	NIGHT	MONTH						
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL		STAGE OF FLIGHT								
SLOBOJAN, M.,		F/O	J39432	P	Uninj.	NO.	DATE		FORCED LANDING							
MOIR, R.G.		P/O	J44553	PP	Uninj.	N112	19-11									
BROWN, B.K.		Sgt.	R205957	Pass	Uninj.	D 14 (REVISED)		TAXYING								
						NO.	CHECKED									
						5		LANDING								
						5										
								TAKE-OFF								
								FLIGHT								
								STATRY								
								FATAL								
								INJ.								
								RAJ								
								M.F.								

PURPOSE OF FLIGHT:

Search for reported a/c crash in St. Lawrence River, north of Matane, P.Q.

NATURE OF ACCIDENT:

Engine began running roughly with drop in r.p.m. and loss of height, flames came through floor. Pilot turned gas off, opened throttle fully, pulled Lux Extinguisher and forced landed, wheels retracted, at dusk visibility in cockpit being completely impaired by smoke. Landing made on very rough terrain.

TECHNICAL OFFICER'S REPORT:

Seizure & breaking of No.3 connecting rod, resulted in damage to crank case.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

FB/AOP/ES/IM/DI/VOKE/AE

CLASSIFICATION:

17. Forced landing

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

ACTION TAKEN:

N11