

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

UNIT F.I.S.		COM. 1	PLACE Trenton, Ont.		DATE 18-12-44	TIME 14.15	
A/C TYPE HARVARD IIB		NO. FE578	CRASH CAT. "D"		S.E. X	M.E.	DAY NIGHT X
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL
FAIRHURST, J. C.,		F/O	J43735	PP	Uninj.		NO. DATE
MC NEILL, R.G.		F/O	J12876	PP	Uninj.		A14 18-12
							D 14 (REVISED)
							NO. CHECKED
							13
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
Wasp	R1340 AN1 AC 42-77/16448 Undamaged		INST. NIGHT		ON TYPE		5000 TOTAL
			61	34	DUAL SOLO	DUAL SOLO	
			98	113	15 13	222 278	
					99 321	214 1354	
					214 440	1568	

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
5
N

PURPOSE OF FLIGHT:

Training - Two students on
"mutual seq."

TECHNICAL OFFICER'S REPORT:

Nil

TCO/PCT/XOV -

NATURE OF ACCIDENT:

While taxiing on runway 130^o
taxied into a snow-plough
coming towards a/c, damaging
port wing of the a/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: