

ACCIDENT CLASSIFICATION

UNIT 19 S F T S Vulvan, Alta.	COM. 2	PLACE 4 mls. south 10 mls east of Vulcan, Alta.	DATE 3-1-45	TIME 1700
A/C TYPE ANSON II		NO. 7311	CRASH CAT. "D"	H.Q. FILE 1100-73-11
		S.E.	M.E.	DAY
			X	X
		NIGHT		

COMMAND
MONTH
STAGE OF FLIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
LANGLOIS, J.H.,	LAC	R257542	PP	Uninj.	NO.	DATE 4-1
					D 14 (REVISED)	
					NO.	CHECKED
					3	

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAIRY
FATAL
INJ.
INJURY

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Jacobs	P25281/13970						
L6MB	S3242/17063	27	20	80	44	135	84

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

RAF

PURPOSE OF FLIGHT:

Practice precautionary landings.

NATURE OF ACCIDENT:

Pupil Pilot carrying out practice precautionary approach in precautionary landing area started overshoot procedure at approx. 15' Opened throttle leaned over to retract U/C and carry out cockpit check, when propellers struck the ground necessitating belly landing.

TECHNICAL OFFICER'S REPORT:

Nil

ILCG/PCL/UOK/B

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

20. Flew into Ground.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed "Error in Judgement."