

CASPIR Aircraft Accident Cards

Serial: 7311

Title: Avro Anson Mk. II serial:7311 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-January-03. Anson II s/n 7311. This accident involved 1 person. Langlois JH

Keywords: RCAFAnson II,7311,19 SFTS,19 Service Flying Training School,Vulcan Alberta,1945-January-03,LangloisRCAF L20

Created: 1945-01-03

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#7311>

ACCIDENT CLASSIFICATION

UNIT 19 S F T S Vulvan, Alta.	COM. 2	PLACE 4 mls. south 10 mls east of Vulcan, Alta.	DATE 3-1-45	TIME 1700
A/C TYPE ANSON II		NO. 7311	CRASH CAT. "D"	H.Q. FILE 1100-73-11
		S.E.	M.E.	DAY
			X	X
		NIGHT		

COMMAND
MONTH
STAGE OF FLIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
LANGLOIS, J.H.,	LAC	R257542	PP	Uninj.	NO.	DATE 4-1
					D 14 (REVISED)	
					NO.	CHECKED
					3	

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAIRY
FATAL
INJ.
INJURY

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Jacobs	P25281/13970						
L6MB	S3242/17063	27	20	80	44	135	84

ACCIDENT CLASSIFICATION

TYPE OF A/C
TYPE OF UNIT
CATEGORY

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61

PURPOSE OF FLIGHT:

Practice precautionary landings.

NATURE OF ACCIDENT:

Pupil Pilot carrying out practice precautionary approach in precautionary landing area started overshoot procedure at approx. 15' Opened throttle leaned over to retract U/C and carry out cockpit check, when propellers struck the ground necessitating belly landing.

TECHNICAL OFFICER'S REPORT:

Nil

ILCG/PCL/UOK/B

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

20. Flew into Ground.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed "Error in Judgement."