

## CASPIR Aircraft Accident Cards

---

**Serial:** 7448

**Title:** Avro Anson Mk. II serial:7448 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1945-January-23. Anson II s/n 7448. This accident involved 1 person. Baal BR

**Keywords:** RCAFAnson II,7448,19 SFTS,19 Service Flying Training School,Aerodrome,1945-January-23,BaalRCAF L20

**Created:** 1945-01-23

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#7448>

ACCIDENT CLASSIFICATION												
UN 19 S.F.T.S. Vulcan, Alta.,			COM. 2		PLACE M.A. #2 Runway				DATE 23-1-45		TIME 12.30	
A/C TYPE ANSON II			NO. 7448		CRASH CAT. "D"		H.Q. FILE 1100-74-48		S.E.	M.E. X	DAY X	NIGHT
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL				
BAAL, B.R.			LAC	R268166	P.P.	Uinj.		NO.	DATE	LG 2 23-1		
								D 14 (REVISED)				
								NO.	CHECKED			
								5				
								22				
ENGINE		ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS							
Jacobs		P17859/9293 N11			INST.	NIGHT	ON TYPE		TOTAL			
L6MB		S17833/9206 N11					DUAL	SOLO	DUAL	SOLO		
					11	-	43	28	91	52		
ACCIDENT CLASSIFICATION												

COMMANDS

MONTH

STAGE OF FLIGHT

FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
INJ. SRB

TYPE OF A/C

TYPE OF UNIT

CATEGORY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

General Seq. Practices.

NATURE OF ACCIDENT:

Port engine failure, pupil carried out single engine landing on Main Aerodrome, but port wheel was not locked down and collapsed on landing.

CLASSIFICATION:

18. Misc Technical

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

TECHNICAL OFFICER'S REPORT:

Failure due to complete seizure of port engine.

LUC / PCDUW / ESNK / UCDC

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Nil