

ACCIDENT CLASSIFICATION

UNIT 7 O.T.U. RCAF Debert, N.S.,	COM. E.,	PLACE M.A., Debert, N.S.,	DATE 22-2-45 TIME 1229Z
A/C TYPE MOSQUITO BXXV		NO. KB 480	H.Q. FILE 1300-KB480
		CRASH CAT. "B"	S.E. M.E. DAY NIGHT X X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
GILLETTE, A.B., CAN.	F/L	J14754	P.	Uninj.	NO. A.19	DATE 22-2
OSBORNE, D.L.,	P/O	G48232	P.P.	Uninj.	D 14 (REVISED)	
					NO. 22	CHECKED <input checked="" type="checkbox"/>
					6	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Merlin 225 P	V343013	Slightly					
Merlin 225 S	V343052	Slightly	52	33	3	205	150 520

TYPE OF A/C	TYPE OF UNIT	CATEGORY	ACCIDENT CLASSIFICATION		COMMAND	MONTH	STAGE OF FLIGHT		
			FORCED LANDING	TAXIING				LANDING	TAKE-OFF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Training - Familiarization and Air Test. Nil

TECHNICAL OFFICER'S REPORT:

LU/PSU ✓

NATURE OF ACCIDENT:

A/C undershot on landing, striking snow drift.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

3. Undershot.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pilot's log book endorsed "Error in judgment".