

ACCIDENT CLASSIFICATION

UNIT 9 B. & G. S	COM. 1	PLACE Stn. Aerodrome Mont Joli	DATE 25-2-45	TIME 12.15
Mont Joli, P.Q.			H.Q. FILE 1100-16-90	
A/C TYPE BATTLE	NO. 1690	CRASH CAT. "D"	S.E. x	M.E. x
			DAY x	NIGHT


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
TAYLOR, J.W.,	P/O	C6703	P.	Uninj.	NO. N 126.	DATE 25-2
					D 14 (REVISED)	
					NO. 3	CHECKED
					3	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Merlin III	166669/23023	44	20	8	418	143	818

ACCIDENT CLASSIFICATION

COMMAND
 MONTH
 STAGE OF FLIGHT

FORCED LANDING
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATARY
 FATAL
 INJ.
 INJURY 3rd
 INJURY 5th



PURPOSE OF FLIGHT:

Test Flight

NATURE OF ACCIDENT:

Pilot misjudged on his approach to land. Rounded out with wheels and flaps down, on trying to go around again his motor cut out and he landed, wheels down, in the deep snow on the side of the runway.

CLASSIFICATION:

3. Undershot.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

TECHNICAL OFFICER'S REPORT:

No 1

OFM/R/ADP/ES/NK/NK/E

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Pilot's log book endorsed.