

ACCIDENT CLASSIFICATION

UNIT 23 W.F.T.S. Yorkton, Sask.	COM. 2	PLACE 2 mls. N. of Hecla Island.	DATE 28-3-45 TIME 1330
A/C TYPE CORNELL I	No. FH 952	CRASH CAT. F/L	H.Q. FILE
		S.E. X	M.E. DAY NIGHT X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
JONES, G.F.J.,	F/O	J37602	F.I.	Uninj.	No.	DATE
					No Sig.	
					D 14 (REVISED)	
					No.	CHECKED
					6	
					8	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Ranger 6-440C-5	27266/2866 N11	75	86	54	217	97	434

ACCIDENT CLASSIFICATION

COMMAND MONTH STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY

7
4
2
1
7
4
2
1

RAF

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Ferrying A/C

Nil

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

Forced landing on Lake due to becoming lost.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pilot's log book endorsed.