

ACCIDENT CLASSIFICATION

UNIT 9 B. & G.S. Mont Joli, P.O.		COM. 1	PLACE Stn. Aerodrome.		DATE 9-3-45	TIME 1545			
A/C TYPE BATTLE		No.	CRASH CAT.		H.Q. FILE 1100-18-88	S.E. X	M.E.	DAY X	NIGHT
		1888							

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
REGAN, J.W.,	WO1	R133615	P.	Uninj.	NO.	DATE
CAMPBELL, L.H.,	AC2	R262931	D.O.	Uninj.	N128	9-3
					D 14 (REVISED)	
					NO.	CHECKED
					2	
					2	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Merlin V.	8310/3767	75	30	5	160	169	461

ACCIDENT CLASSIFICATION

COMMAND

MONTH


STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATUTORY
FATAL
INJ.
3RD
5
N

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Scheduled Target Towing.

NATURE OF ACCIDENT:

Pilot landed on runway with wheels apparently locked down and immediately prior to turning off one oleo leg collapsed. Selector not touched and Pilot switched off without horn blowing. Horn blew on check later.

CLASSIFICATION:

5. U/C Failure.

SECONDARY OR CONTRIBUTORY FACTORS:

32. U/C Drill - in air.

TECHNICAL OFFICER'S REPORT:

Obscure.

TUC/PCDUW/UCDT

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Nil