

PURPOSE OF FLIGHT:

Local Circuits .

NATURE OF ACCIDENT:

Student Pilot attempting to come up
slipway in Canse 11100, taxied into
JX580, which was moored in the Bay.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

Nil

MULT
TCR/PCT
TMA/XA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Pilot's log book endorsed.