

## CASPIR Aircraft Accident Cards

---

**Serial:** 11003

**Title:** Consolidated Canso A / 2F serial:11003 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1945-June-12. Canso s/n 11003. This accident involved 14 people. Aitkens FO, Balbraithe DA, Bomford NH, Brown TJ, Dieringer JP, Doodson CW, Gingras FP, Hunter GR, Labbe R, Johns WH, Gauthier RJ, Veitch JE, Standring DM, Willis RC

**Keywords:** RCAF Canso , 11003, 2 , 2 TSU, Aerodrome, 1945-June-12, Aitkens, Balbraithe, Bomford, Brown, Dieringer, Doodson, Gauthier, Gingras, Hunter, Johns, Labbe, Standring, Veitch, Willis RCAF L20

**Created:** 1945-06-12

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000357#11003>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT: TCD/UBF

Testing radio altimeter installation

NATURE OF ACCIDENT:

Hydraulic system failed while taxiing down wind. In Attempt to ground loop to prevent running into fence and drainage ditch stbd. mainplane struck corner of building.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Johns, W.H. W02 R50568 WEM Uninj.  
Gauthier, R.J. F/S 935 Machinist.  
Veitch, J.E. Cpl. R88891 Equip.  
Standring, D.M. IAC R84806 Equip.  
Willis, R.C. IAC R260506 ARM

CLASSIFICATION:

11.Others

SECONDARY OR CONTRIBUTORY FACTORS:

36.Brake failure.

ACTION TAKEN: