

ACCIDENT CLASSIFICATION												
UNIT 23 E.F.T.S. YORKTON, Sask.		COM. 2		PLACE Taxi Strip, M.A.,		DATE 11-7-45		TIME 0930		COMMAND		
A/C TYPE CORNELL CORNELL		No. 947 975 - D		CRASH CAT. "D" "D"		H.Q. FILE 1100-9-47		S.E. X				M.E. X
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		MONTH		STAGE OF FLIGHT	
HALL, G.S., GB.		LAC	1876571	P.P.	Uninj.		NO. DATE A.49 12-7		D 14 (REVISED)			
STACEY, J.R.,		F/O	J36249	F.I.	Uninj.		NO. CHECKED 2		1		FORCED LANDING	
HEYHURST, D., GB.		LAC	1876571	P.P.	Uninj.						TAXYING	
											LANDING	
											TAKE-OFF	
											FLIGHT	
											STAT'RY	
											FATAL	
											INJ.	
											3RD	
											INJURY	
											RAF	
ACCIDENT CLASSIFICATION												

PURPOSE OF FLIGHT:

Training Flight.

TECHNICAL OFFICER'S REPORT:

Nil

TCA/PCT
TCA/XA

MULT

NATURE OF ACCIDENT:

While being taxied, A/C 975 struck parked a/c 947 causing damage to both machines.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44